

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11244



Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080021-0

RECEIVED FROM

DATE REC'D. 2-11-59

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO. S.O. NO.
	322		41	0	10				
96	DRAWING NO. AND DESCRIPTION					QUANTITY		REMARKS	
	731410- B Connector Modified					ACCEPTED 96		REJECTED	
Ship per #35927									
<div style="text-align: right;">    </div>									
RECEIVED BY	INSPECTED BY		DATE 2/12/59		REJECTS RETURNED ON SHIP MEMO NO.				

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11247



2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 2-12-59

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO. S.O. NO.
	323		17	B	11	1			
12	DRAWING NO. AND DESCRIPTION					QUANTITY		REMARKS	
	731455-2 Spring Lamp					ACCEPTED 12		REJECTED	
Ship per #35928									
<div style="text-align: right;">    </div>									

RECEIVED

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080021-0

BY

PMC-1089